# Regarding Quality Control Certificate

**Name of Work:** **Impovements to Roads, Drains and Construction of Culverts at MS Palya 2nd Stage Masidhi Main Road and Cross Roads in Ward No. 11 (Kuvempunagara), Vidyaranyapura Sub Division.**

**Job No:** **011-14-000011**

**Work Order No:** **492/22-02-2014**

**On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT & H at this stage is not feasible since this work was executed ------ Year back.**

**Executive Engineer** 26/3
**Byatarayanapura Division**
**Bruhat Bangalore Mahanagara Palike**